| DEPARTMENT OF HOMELAND SECURITY MISLE Activity Number: | | | | |
|---|---|---|--------------------|--|
| U.S. Coast Guard PORT STATE CONTROL REPORT OF INSPECTION - FORM A* | | | | 6894432 Exam Type: |
| In accordance with the IMO's Procedures for Port State | Control | and the International Chin | A | I |
| Reporting Country: United States of America | 2. Name | 101 | & Port Facili | y Security (ISPS) Code |
| 3 Flag of Ship. Liberia | 4 Ship Tune Code | | E Call Cia- | |
| 6 IMO Number: 9122999 | 7 Crupp Terror | | 5 Call Sign D5 Hm9 | |
| 9. Yr. of Build: 1975 10 Date of Inspection 31JAN262 | 11 P | 17,113 | 8. Deadweight: | |
| 12. Classification Society | 13. Detention Info ** a) Date/Time Imposed: | | | |
| Niepon Kaiji Kyekai | | b) Date/Time Released: N (A | | |
| 14. Ship Management Information (include address): BETA MARITIME CORP 57 AKH Miasuli 5th Floor 185 36 Pinneus, Greece Charterer: | | | | |
| | | | | |
| ISM DOC Company w/IMO Company #: BETA MARITYME CORP / 652 32 63 | | | | |
| Owner w/IMO Company #: Operator w/IMO Company # | | | | |
| Smooth Abuigation 5.4. 15823232 | | | | |
| Relevant Certificates/Documents**: | | BETA MARITIME | CORP / S | 7823263 |
| 1) issuing | - | | c) Date of Issu | e and Explry |
| 2) | | | | |
| 3) | | | | |
| 4) | | | | |
| Information on last intermediate or annual survey/audit ** Date | | | | |
| 1) | | Place | | |
| 2) | | | | |
| 3) | | | | |
| 4) | | | | |
| Check all applicable for 16-19 below: 6. Deficiencies Identified: No Yes (II ves see Form 8 (C | | | | The state of the s |
| 7 Major Control Action: No Detention Expulsion 8. Priority: PI PI B NPV | n 🗆 De | nial of Entry: For Safety PS I ISPS II ISPS II ISPS/Security Related Dr | n - 3 | |
| ovided to: ALLAHAWANT KHANER (Printed name of Master/Vessel representative) | Signat | ura) | 1 | |
| ame of SCO Finited name of duly authonized PSCO of reporting authorities | Signati | ure | Cartines | |
| suin c Unit Manue a nd Address. Copies | forwarded | to: Check as appropriate | Ra | viewed by Supervisor |
| 1050 Register St. | gent [| Ship Management | Name | |
| North Charleston, SC 20405 | lag State | Recognized Organization | | |
| | ecognized | Security Organization | Date: | |
| This inspection report has been issued solely for the purposes of informing the report shall not be construed as a seaworthiness certificate in excess of certificate in excess of certificate. | e master and ficates the si | other port States that an inspection hip is required to carry | by the USCG has | Taken place. This inspection |

CG-5437A (02/16) Slock No CG7530-01-GF9-0003

Vessel Copy

DEPARTMENT OF HOMELAND SECURITY MISLE Activity Number: 689 4422 U.S. Coast Guard PORT STATE CONTROL REPORT OF INSPECTION—FORM B Exam Type PSCB/ISPS In accordance with IMO Port State Control Procedures and the International Ship & Port Facility Security (ISPS) Code 1. Reporting Country United States of America 2 Name of Ship EVOLUTION 3 IMO Number 9122899 4 Date of Inspection. 31 JAN 2020 Place of Inspection Charloston, SC 6 Nature of Discrepancy Code Description Cite (Convention) (Action Taken)2 01 07185 Doors required to be solf-closing shall 74 SOLAS (1997 El.) 40 ac not be fitted with hold-back hooks. CH. IP-2 / Agg. 47.2 Door leading to the bridge and the two doors in the galley were fitted with held-back hooks pasing as a fine and smake hazard to the ship and crew. 02 07/03 where "A" class divisions are penetrated 7450LAS (1897 Bd.) for the passage of electric cables, pipes, CH. I-2 | Rag. 18-11 trunks, ducts, etc., arrangements shall be made to ansure that the five registence is not impaired penatrations within moin vertical for electric cables found not sealed properly thus impairing five resistance also observed not self-closing After any survey of the ship under regulation 10 74 sours (2014 B.C.) has been completed, no change shall be made in the structural arrangements machinery, equipment and other items covered by the survey without the sanction of the Administration. 02 doors in gally storage area bound with from emergency escape mechanism 5364 Сору (Printed name of Master/Vessel representative) Provided to: Signature: Name of Gosor E. Santacana PSCO: Signature: (Printed name of duly authorized PSCO of reporting authority) Issuing Unit Name and Address: Copies forwarded to: Check as appropriate Reviewed by Supervisor Name Agent Agent ☐ Ship Management ☐ Flag State ☐ Recognized Organization Date Recognized Security Organization This inspection was not a full survey and deficiencies tisted may not be exhaustive. In the event of a detantion, it is recommended that a full survey is carried out and all deficiencies are rectified before an application for re-inspection is made. Codes are for action taken, see below: (Note, code r bers are derived from international harmonization. U.S. upon similar codes and those are reflected below t 10 Daticiency Rectified Rectify deficiencies prior to departure 20 Ship expelled Rectify deficiencies by next port 60 Rectify deficiencies prior to movement 25 Ship denied entry 16 Rectify deficiencies within 14 days 40 Rectify deficiencies prior to next U.S. port after sailing fereign To the satisfaction of RO/RSO Rectify deficiencies within 30 days 30 Ship detained To the satisfaction of the Administration

CG-5437B(02/16) Stock No. CG7530-01-GF9-0004

Vessel Copy

To the satisfaction of the U.S. Coast Guard